



IN-SERVICE ESTIMATE



Equipment Number: CGMU5049156
ISO: 45R1

Repair Company: PROGECO LLP
CMA-CGM : 40 RH

Estimate No	: WOBH24020151	Date of Manufacture	: 01-DEC-2010
Estimate Date	: 28-SEP-2024	CSC Valid	: ACEP
Estimate Created By	: PROGECORFR-NSA	Grade	: GC (General Cargo)
Remarks	: MBL No = DBA0353767 CV = 03 Oct 2024 CDL = 20000.00		

S	L.NO	LOC	COMP	REP	DAM	MAT	LEN	W/H	UNIT	QTY	RES	MAN	HRS	MAN	COST	MATL	COST	TOTAL	COST
		T-Floor Assembly - Water Wash - Dirty																	
	1	IXXX	TFA	WW	DY	MU	0.00	0.00	CMT	1	0	0.00		0.00		350.00		350.00	
		Panel-Outer Cladding - Patch - Improper Repair																	
M	2	RXXX	POC	PT	IR	MU	30.00	15.00	CMT	1	0	1.00		75.00		350.00		425.00	
		Panel-Joint Capping - Seal/Reseal - Loose Component																	
	3	RHXX	PJC	SE	LO	MU	300.00	0.00	CMT	1	0	0.20		15.00		210.00		225.00	
		Panel-Joint Capping - Seal/Reseal - Loose Component																	
	4	LHXX	PJC	SE	LO	MU	300.00	0.00	CMT	1	0	0.20		15.00		210.00		225.00	
		Gasket Assembly - Section - Cut																	
	5	DB4N	GTA	SN	CU	MU	15.00	0.00	CMT	1	0	0.50		37.50		60.00		97.50	
		Rail - Assembly - Surface preparation and paint - Corroded/Rusted																	
D	6	LHXX	RLA	PS	CO	MU	30.00	0.00	CMT	4	0	0.80		60.00		80.00		140.00	
		Panel-Outer Cladding - Weld - Corroded/Rusted																	
	7	LX67	POC	WD	CO	MU	15.00	0.00	CMT	5	0	1.25		93.75		375.00		468.75	
		Header Extension - Weld - Cut																	
	8	TX1N	HEP	WD	CU	MU	15.00	0.00	CMT	1	0	0.25		18.75		40.00		58.75	
		Panel-Outer Cladding - Weld - Cut																	
	9	TX9N	POC	WD	CU	MU	15.00	0.00	CMT	2	0	0.50		37.50		150.00		187.50	
		Panel-Outer Cladding - Patch - Improper Repair																	
D	10	TX67	POC	PT	IR	MU	45.00	30.00	CMT	1	0	1.75		131.25		975.00		1,106.25	
		Panel-Outer Cladding - Patch - Improper Repair																	
D	11	TX67	POC	PT	IR	MU	30.00	30.00	CMT	1	0	1.25		93.75		675.00		768.75	
		Temperature Display - Replace - Wear and Tear : TMEP DISPLAY DEFECTIVE TO REPLACE PN: 12-00433-00R																	
	12	MCNN	TDI	RP	WT	ZZ	0.00	0.00	CMT	1	0	1.00		75.00		13,950.00		14,025.00	
		Refrigerant Charge - Recharge - Low fluid level : GAS LESS TO CAHRGE 2KG R134A																	
	13	MPNN	FCH	CH	LF	ZZ	0.00	0.00	CMT	2	0	0.50		37.50		1,900.00		1,937.50	
		Cargo Container - STANDARD PTI - Unspecified																	
	14	MXNN	MCO	PI	ZZ	ZZ	0.00	0.00	CMT	1	0	0.00		0.00		1,000.00		1,000.00	

Total Man Hours	5.40
Total Man Hour Cost	5.40
Total Material Cost	18,595.00
Total Flat Rate Cost	1,350.00

Total Cost In Base Currency	226.18	USD	Total Cost	19,000.00	INR
			Original Estimate Cost	21,383.75	INR



IN-SERVICE ESTIMATE



Equipment Number: **CGMU5049156**
ISO: 45R1

Repair Company: **PROGECO LLP**
CMA-CGM : 40 RH

Printed by : MnR Organization: A0 INDIA
User Name: S00821962